## Approved For Release 2000/09/01 : ARD 81B00878R001400030025-2

SAPC 24300 Cy / of 8

7 February 1958

MEMORANDUM TO: PROJECT DIRECTOR FOR DEVELOPMENT
AND PROCUREMENT




SUBJECT

: Project Readout Equipment

1. A meeting on the above subject was held at Headquarters on 7 February 1958 with the following personnel in attendance:

25X1A

25X1A



- 2. The various readout racks were discussed with the following results:
  - a. A, Bl, and B2 racks have been debugged and are satisfactory for use in their present state.
  - b. The C rack is satisfactory in its present state; however, an approved modification to allow tape speeds of 30 and 60 IPS has not been incorporated in the racks to date. It requests that R-W prepare Field Modification Kits to allow this modification to be accomplished as soon as possible. It is the understanding of all concerned that funds have already been allocated for this modification. Will look into this while on TDY to R-W next week. Will also investigate from this end.

25X1A

25X1A

25X1A

25X1A

c. The D rack is under development by and work is progressing satisfactorily. It is concerned, however, about recent
Soviet electronic developments and fears that we may have to add to
the channel capacity of the equipment. Most of the information on
new Soviet developments has been brought to light by our System IV
missions.

25X1A

- d. The E rack is not yet in our hands. Progress by R-W has been extremely slow on this equipment. will look into this subject the week of 10 February.

as soon as possible.

- 2 -


- f. The G, H, J, and K racks are satisfactory in their present state. This endorsement applies only to the racks presently in use at NTPC. These racks have been debugged by RW and Blue Room personnel.
- recommends that the balance of the L rack procure-25X1A g. ment be cancelled. A change in operational concept has greatly reduced the need for this equipment. The completion of 15 to 20 System IV missions per month would dictate the use of the F rack concept. However, the impact of 1 or 2 System IV missions per month does not justify the use of this equipment. Is investigating this problem.
- 25X1A states that a serious problem exists in the M and h. N racks with regard to AGC readout. He recommends that provide a modification to correct the AGC deficiency. This modification will require the use of a multiple pen brush recorder to attain the desired results. The N rack must allow normal and 4 times normal speed to 25X1A will check into the tape speed quesfunction properly. will furnish

tions at RW on 10 February 1958. 25X1A guidance on required modifications.

25X1A Ma,jor USAF 25X1A

PCS/DCI/LSJ:pb

25X1D



Approved For Release 2000/09/01 : CIA-RDP81 000878R001400030025-2 1. NAM rack # 12,700 \*/ N - DC output \$2,500 prd \$ 25000 1500 2m - completely to N + 2,500 60%. 2M - Fuguet response 7,700 # 15000 IN - 90% completed 2M-17THER 24 TH Feb I Church to see 3 Model Bunt with kater to chit 3's commy low Approved For Release 2000/09/01 : CIA-RDP81B008787901490090025-2

be given action on this one because it 25X1A